



TRACKING DOCUMENT



Repair Order Number

Repair Order Number RE00084269	Description/Serial Number A6218978	Repairman - Robert Frink
Account # - R-	Model 700 Center Fire with 24 inch barrel Caliber: 300 WIN MAG BDL W/SCOPE	Date Received - 9/3/2004
Customer DAVID HOFIUS 305 TOURNAMENT TRAIL CORTLAND, OH 44410 US		Estimate Date - 8/30/2004 Current Date - 9/10/2004
Phone (H) (330)-638-8193 Phone (W)		Return To DAVID HOFIUS 305 TOURNAMENT TRAIL CORTLAND, OH 44410 US
	Fax	
	Email	

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M992	FIRED WHEN TAKEN OFF SAFE	M238	CLEAN & INSPECT (SAFETY PROGR.
		M239	REPLACE TRIGGER ASSEMBLY

Repair					
Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116	GR-LABOR	20	20	0	N
4000118	GR-CLEAN	1	1	0	Y
4000119	GR-TEST	1	1	0	Y
Service Total:		22	22	0	

Condition	Test with slave recoil pad.				
Problem/Notes	Could not duplicate. Trigger assembly is very dirty and has some partially dried lubrication. Replace complete trigger assembly under Bolt Lock Safety Program.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date