

Altered adjustments

Install new TA and  
clean action \$20.00  
under Bolt lock modification  
program.

FCS

11/30/2004

Serial Number: 6553935

Model: 700



RE00088107

This model 700 discharged  
on its own when I took  
off the safety.  
When I called they told me it may  
be as simple as cleaning the trigger  
mechanism, but they would like me  
to send it in so you could look at it.

88107

Thank-you

Art Hank (802-434-4408)

102 Edge Wood Ln.  
JONESVILLE, Vermont  
05466

Please see full prescribing information, including BOX WARNING, on last pages of pad.  
© Janssen Pharmaceutica Products L.P. 1999

01-PR-736

1007  
4015

5/2/78