

Ted Hillary M/721-3006 Ser#64452

- Pound pull screw backed out - as rec'd
- Safety detent spring out of position - as rec'd
- Pound's pull screw is backed out so far that it does not return trigger and connector. Trigger is free to move 'no load' on it at all.

Pound's pull has approx 2 to 2 1/2 thread engagement in housing as rec'd.

- ~~See~~ ^R ~~spring~~ Trigger pound's pull spring is present in housing as rec'd.

- Sealant on rear engagement and overtravel screw but none on pound's pull screw.