

R943012C

Ted Hillary M/121-3006 Ser#64452

- Pound pull screw backed out - as rec'd
- Safety detent spring out of position - as rec'd
- Pound pull screw is backed out so far that it does not return trigger and connector. Trigger is free to move 'no load' on it at all.

Pound pull has approx 2 to 2 1/2 lb engagement in housing as rec'd.

- ~~See~~ ^R ~~spring~~ Trigger pound pull spring is present in housing as rec'd.

- Sealant on rear engagement and overtravel screw but none on pound pull screw.