

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-30120

INITIAL FPS	CUSTOMER ORDER NO.	ATTN: JACK KAST RECOIL PAD NOT OF OUR MFG.			
DATE RECEIVED 10/20/94	DATE OPENED 10/21/94	DATE CODE AUU 3-49	SERIAL NUMBER 64152	NEW SERIAL NUMBER	MODEL AND GRADE 721 30-06
ACCESSORIES W/STUDS					

FROM:

HILLARY, TED
34414 BOND ROAD
LEBANON

OR 97355

SHIP TO:

HILLARY, TED
34414 BOND ROAD
LEBANONOR
97355

CUST NO: 106294 C.D.D.L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C 059015	WRITE ☐	PROM. DATE	ESTIMATED	VIA V562345
----------------	------------------------------	--------------------------------	------------	-----------	----------------

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

* Stock altered, wood added to comb
* Receiver has extra tapped hole on rear bridge.

[Signature] 10/21/94

Hold for reply in P.S.

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE						
TRIGGER GROUP						
BOLT ASSY.						
BARREL ASSY.						
REC. ASSY.						
WOOD						
METAL						
MAIN FAULT: <i>Mfg. Mar 1949 Trigger and connector does not return under</i> <i>sear because pounds pull screw has been backed out</i> <i>so far that the return spring does not engage.</i> <i>Exchange trigger assy. for a mil spec trigger assy. at n/c strictly</i> <i>as a gesture of good will and to restore customer confidence</i> <i>in the rifle.</i>						

PARTS

COMMENTS

Safety detent spring out of positio
as rec'd

Sear coated with old dried oil

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94

PS03267