

Repair Order Number



Repair Order Number RE00051730	Description/Serial Number ML095751	Repairman - Robert Frink Date Received - 9/9/2002
Account # - R-	Model 700ML Center Fire Caliber: 50 W/ SCOPE	Estimate Date - Current Date - 9/13/2002
Customer CECIL HATFIELD 5572 OUARTERPATH GATE VIRGINIA BEACH. VA 23455 US	Return To CECIL HATFIELD 5572 OUARTERPATH GATE VIRGINIA BEACH. VA 23455 US	
Phone (H) (757)-460-9361 Phone (W)	Fax Email	

Reported		Problems Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M992	FIRED WHEN SAFE WAS REMOVED		

Material # MaterialDesc		Repair			
		Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F99294	700 ML SS TRIG ASSB	1	1	0	Y
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
Service Total:		0	0	0	

Condition	REC'D W/ POOR FINISH ON TRIG GUARD.				
ProblemNotes	Altered adjustments. Broken connector. Install new trigger assembly and repair as needed at n/c. FLS 9/11/02.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date


16 LBS 1 OF 1

REMINGTON ARMS CO INC
800 243-9700
14 MOEFLER AVE
ILION NY 13357

SHIP

TO:

CECIL HATFIELD
5572 QUARTERPATH GATE
VIRGINIA BEACH VA 23455




VA 234 9-05



UPS GROUND

TRACKING #: 1Z 114 813 03 1194 2799



BILLING: P/P

INV#: RE00051730

ASC 05.00 J69K/J64K 16.0A 01/2002