

WR = 8/97

DEAR REMINGTON Dealer

While HUNTING with MY GUN,
I took the SAFETY OFF AND THE
GUN FIRED. BEING IN the WOODS
FOR A WEEK A FRIEND MADE ADJUSTMENT
ON the TRIGGER ASSEMBLY. IT WORKED
BUT DIDN'T LAST LONG BEFORE
IT HAPPEN AGAIN. I NOW KNOW
I SHOULDN'T HAVE TOUCH THE GUN
AND SENT IT RIGHT BACK TO THE
DEALER. PLEASE FIX THE GUN. IF
YOU HAVE ANY QUESTION'S FEEL
FREE TO CALL ME. 757-460-9361

Altered adjustments
Install new TA n/c
Repair as needed
Charge 230145
FLS 9/11/02

THANK YOU
Cecil HATFIELD
5572 QUARTERPATH GATE
VA, Beach VA.
23455

Serial Number: **ML095751**

Model: **700ML**



RE00051730