

STATE OF MARYLAND
DEPARTMENT OF PUBLIC SAFETY AND CORRECTIONAL SERVICES
DIVISION OF CORRECTION

PARRIS N. GLENDENING
GOVERNOR
ATHLEEN KENNEDY TOWNSEND
LT. GOVERNOR
STUART O. SIMMS
SECRETARY

F R O M	Hagerstown Regional Training Facility C/O Roxbury Correctional Institution 18701 Roxbury Road - Hagerstown, Maryland 21746	AGENCY NAME & ADDRESS
	LT. TROYL IMES <i>[Signature]</i>	NAME & TITLE
	DEFECTIVE REMINGTON MOD. 7	SUBJECT

WILLIAM W. SONDERVAN, ED.D.
COMMISSIONER
FRANK C. SIZER
DEPUTY COMMISSIONER
LLOYD L. WATERS
WARDEN MCI-H
JOSEPH P. SACCHET
WARDEN RCI
J. MICHAEL STOUFFER
WARDEN MCTC

To: DENNIS SANITA

Date: 1-3-01

DENNIS, I AM SENDING BACK MY REMINGTON MOD. 7 IN 243 CAL. TO BE CHECKED FOR SAFETY. I PURCHASED THE WEAPON ON NOVEMBER OF 2000. THIS WAS 3 DAYS PRIOR TO DEER SEASON IN MY HOME STATE OF WEST VIRGINIA. I TOOK THE WEAPON TO THE RANGE AND ATTEMPTED TO CHAMBER A REMINGTON 100 GRAIN CORELOC CARTRIDGE, THE BOLT WOULD NOT CLOSE SO I TRIED ANOTHER CARTRIDGE FROM THE SAME BOX, STILL WOULD NOT CLOSE. I THEN GOT A DIFFERENT BOX OF REM. 100 GRAIN CORELOC WITH A DIFFERENT LOT #. THE BOLT STILL WOULD NOT CLOSE SO I PUSHED HARD AND THE BOLT CLOSED AND THE WEAPON DISCHARGED. I UNLOADED THE WEAPON AND LOOKED AT THE BOLT. THE BOLT APPEARED TO BE NOT PROPERLY FINISHED AND THE SPENT SHELL WAS BADLY WORN WITH SMALL PIECES OF BRASS SHAVED OFF. I THEN TOOK SOME GUNSMITHING TOOLS AND FILED THE AREA NEAR THE BOLT FACE AND EXTRACTOR AND STONED IT UNTIL IT WORKED. IT SEEMS TO BE WORKING FINE NOW. I FEEL REMINGTON STAFF SHOULD HAVE CAUGHT THIS AT THE FACTORY. DO THEY EVEN TEST THESE WEAPONS ? I ALSO HAD TO REMOVE THE SCOPE/MOUNTS TO SEND THIS WEAPON BACK. I OWN SEVERAL REMINGTONS AND HAVE NEVER SEEN A MISTAKE FROM THE FACTORY LIKE THIS BEFORE. IF YOU NEED A CHARACTER REFERENCE CALL RICK JOHNSON AT REMINGTON IN ARKANSAS AT (501) 676-4208. IF YOU HAVE ANY QUESTION PAGE ME AT (301) 714-6955.


RETURN THE WEAPON TO THE ADDRESS ABOVE. THANKS

1008
4040
1/9/01 Bolt would not close, pushed hard and it discharged.
Unable to duplicate
Date Code 11/99
Disassembled completely tug arm.
Checked completely
Replace tug arm at no charge
Change 230145

Serial
Number:

7755934

Model: 7



RE00020222

TROY TMS

WVA.

m/7

FBC

Bolt Close Hand

1008
4040

12/8/00

ARS label Makers