

Repair Order Number



Repair Order Number
RE00095232

Description/Serial Number
B6312773

Repairman - Herb Brown
Date Received - 4/5/2005

Account # - R-

Model 700 Center Fire Caliber: 7 MM
REM MAG BDL

Estimate Date - 4/1/2005

Current Date - 4/8/2005

Customer
JERRYS SPORTING GOODS
RT 1 GEORGETOWN RD

Return To
JERRYS SPORTING GOODS
RT 1 GEORGETOWN RD

HORNER, WV 26372 US

HORNER, WV 26372 US

Phone (H) (304)-452-8227

Fax
Email

Phone (W)

Reported

M123 FORWARD TO PRODUCT SERVICE
FOR INSPECTION
M992 FIRES WHEN PUSHED OFF SAFETY

Problem

Found

M123 FORWARD TO PRODUCT SERVICE F

Material # Material Desc

Part

F26345 700 TRIG ASSB RH

Part Total:

Service

4000104 ARMS SERV SHIPPING & HANDLING
4000116 GR-LABOR
4000119 GR-TEST
4000294 GR-CHECK TPA

Service Total:

Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
1	1	0	Y
1	1	0	
0	0	0	Y
20	20	0	N
1	1	0	Y
1	1	0	Y
22	22	0	

ProblemNotes

Could not duplicate customer concern. Trigger assm. very dirty. Replace trigger assm. under bolt lock program for \$20.00.

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date