

Remington

Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700 BDH	Serial Number: 6216830
Name: RONALD L. JAMES	Date of Purchase: 1969-ORIGINAL OWNER
Address (no PO Boxes): 12064 PLATINA ROAD	
City: IGO/ONO	State: CALIF Zip: 96047-300
Phone (Daytime): 530-396-2294	Fax: _____
E-mail Address: ONO RONNI@OAL.COM	

Please describe your problem:

IN LAST 20 YRS THIS FIREARM HAS FIRED WHILE IT WAS BEING UN LOADED. IT HAS HAPPENED ABOUT HALF THE TIME - SO WATCH OUT

Additional Information: (Ammo type, brand, handload specifications, etc.)

6.5MM FACTORY LOADS
FIREARM HAS BEEN FIRED APPROX-
MENTLY 200 TIMES (Please call for details)

NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.

① WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

- :: Record the serial number of your firearm before sending it.
- :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)
- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Could not duplicate,
gummy sticky residue,
improper maintenance

Quartz new TA under
Bolt Lock Modification program \$20.
<http://www.remington.com/support/repairsvc/repairform.htm>

43680

FLS 3/26/02

03/07/2002