

FROM Richard Jettow
1095 Polaris
Portland Texas ZIP 78374

TO Remington Arms Company Inc
Thon Firearms Plant
Action Product Service
Thon New York ZIP 13352

Richard Jettow

Homo 361 643 3077

1095 Polaris

Mobil 570 8090

Portland Texas 78374

55613

I Try To Pull the tiger And the did not fire so when I went to unbolt the Bullet the Bolt would not open so I Put it Back in safe A deer step out I Put the Crosshair when it went off when I want from safe to Fire without Touching the Tiger I quit using

P.S

I own 137

This gun when it happen twice other Remington they don't shoot like this Thanky Richard

Could not duplicate.

Improper maintenance; underside of Action & TA extremely dirty & heavily oiled.

Clean Action & Install new TA

Quote customer \$20.00 under bolt lock Modification program.

FLS 6/14/02

RE00047958



Model: 700

6748902

Serial Number: