

Remington.

Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

| | | |
|---|------------------------|------------|
| Model Number: 700 | Serial Number: 6384589 | |
| Name: Bob Jones | Date of Purchase: 1980 | |
| Address (no PO Boxes): | | |
| # 3 La Granja Circle | | |
| City: Hot Springs | State: AR | Zip: 71909 |
| Phone (Daytime): 501-984-4141 | Fax: 501-984-4142 | |
| E-mail Address: bob@carpetbarn.net | | |
| Please describe your problem: Gun Discharges when unloading or loading | | |
| | | |
| | | |
| | | |
| | | |
| Additional Information: (Ammo type, b | | |
| | | |
| | | |
| | | |

Serial Number:

6384589

Model: 700



RE00051214

Date Code
RT 11/70

NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.

Ⓢ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

- :: Record the serial number of your firearm before sending it.
- :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)
- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

8/24/82 Action & trigger assembly caused with study inspection.
Clean Action & replace trigger. \$20.00
Quote

AREGO'S PAWN, INC.
1558-G Airport Road
Hot Springs, AR 71913
501-760-2330

Welcome to Remington Country!

Remington.

Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

Serial Number: 1984589