

I AM RETURNING THIS MODEL 700 TO HAVE IT CHECKED
BECAUSE IT HAS DISCHARGED TWO DIFFERENT TIMES BY
SIMPLY PUSHING THE BOLT FORWARD AND DOWN.

AFTER THE FIRST TIME THIS OCCURRED I TOOK IT
TO A LOCAL GUN SMITH TO HAVE IT CHECKED. HE
COULDN'T FIND ANYTHING WRONG, BUT THOUGHT THERE
MIGHT BE AN OIL BUILDUP IN THE TRIGGER MECHANISM.
HE CLEANED EVERYTHING AND IT WORKED FOR THE FALL
HUNTING SEASON.

AFTER BEING STORED FOR A YEAR, IT HAPPENED
AGAIN. AT THE BEGINNING OF THE NEXT FALL HUNTING SEASON.
AFTER WORKING THE BOLT IN & OUT SEVERAL TIMES, IT
STARTED WORKING AGAIN.

IF I CAN BE OF ANY HELP PLEASE CALL ME
AT 602-445-5892.

Thank You

Mike Jackson

ATT- JACK KAST

not enclosed. Exchange
price of good will AND TO
DILL MANUFACT 3 1/4 to 3 3/4
d. seal left was .008
and spray rusty

OFFICE COPY

RD6925 REV. 1/94