

RECEIVING AND ESTIMATING REPORT

COMMENTS

ATTN JIM STEKL

INITIAL CUSTOMER ORDER NO.

LCS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

MODEL AND GRADE

ORDER

05/20/91

05/23/91

BU 1-71

6492205

700

270

ADL

R

91-11200

ACCESSORIES

SCOPE BASE

L/REAR SIGHT

FROM:

JACKALOPE GUN SHOP
1048 SOUTH 5TH ST.
DOUGLAS
USA

WY 82633

SHIP TO:

JACKALOPE GUN SHOP
1048 SOUTH 5TH ST.
DOUGLAS
USA

WY

82633

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

REPAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

GUN CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

"... This rifle fires when safety is released on the bolt lockout."

MAIN FAULT

No fault found - cannot duplicate above complaints. Trigger pull 5 pounds rear - lift .009". However, removal of action from stock revealed excessive dirt and oil on bottom of action and on trigger assembly. Rifle has not been properly maintained.

PARTS

Offer to return rifle with present trigger assembly, after cleaning, or offer to replace trigger assembly at 1/2 normal cost, as a gesture of good will, if it will better restore confidence in the rifle.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE