

RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL CUSTOMER ORDER NO.

LCS 7121

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
12/21/90	01/02/91	EB 10-81	B6350291	700 30-06 LH/BDL	R 91-00069

ACCESSORIES W/STUDS SCOPE BASE L/ REAR SIGHT

FROM: SHIP TO:

JOHN Q'S QUALITY GUNSMITHING
5165 AUBURN BLVD
SACRAMENTO CA 95841

JOHN Q'S QUALITY GUNSMITHING
5165 AUBURN BLVD
SACRAMENTO CA 95841

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/> CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	---	------------	-----------	---------

REPAIR CHARGE	TAX	INSURANCE	UPS -	PARCEL POST	TOTAL
---------------	-----	-----------	-------	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST *gun fired while customer was closing bolt*

MAIN FAULT *Cannot duplicate complaint - Trigger and safety assembly function properly in all respects. Trigger pull 5 1/2 pounds; rear-left .008 in. Left cannot be made to malfunction in anyway.*

PARTS *Offer to return rifle as-is, we can install a new trigger assembly at 1/2 normal cost, as a gesture of good-will, if it will better restore confidence in the rifle.*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE