

RECEIVING AND ESTIMATING REPORT

COMMENTS

CUST NO: 048134 C.O.D

ATTN D VALENT

INITIAL
JJM

CUSTOMER ORDER NO.

DATE RECEIVED 08/22/91

DATE OPENED 08/27/91

DATE CODE BL 1-91

SERIAL NUMBER C6626770

MODEL AND GRADE 700 223

ACCESSORIES W/STUDS

L/SIGHTS

ORDER R 91-16815

FROM:

SHIP TO:

JOHNSON, ROBERT W, III

RR 5 BOX 82

OSKALOOSA IA 52577

USA

JOHNSON, ROBERT W, III

RR 5 BOX 82

OSKALOOSA IA 52577

USA

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐ CLEAN/TEST

PROM. DATE

ESTIMATED 8-28

VIA UPS

REPAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

GUN CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

take safety off & it automatically fires

MAIN FAULT

As received rifle would not cock. Disassembly revealed chipped edges on

connector and rear safety cam. Further examination revealed this damage was

caused from pierced primers - usually associated with misprimed rounds.

Note* - As received, magazine bar was re-installed upside down which will affect

parts

Send quotation for new trigger assembly -

current assembly cannot be

repaired.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

BWT

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

DATE

DATE

DATE

DATE

DATE

DATE

DATE

DATE

DATE

DATE

DATE

DATE

DATE

DATE

DATE

DATE

DATE

DATE