

Setup, etc.

JAY'S SPORTS

XC
Suggest
1/2 OR FULL PAY
FOR NEW FIRE
CONTROL!

FINGERPIECE OF TRIGGER HAS BEEN
BADLY BENT DOWN AND REARWARD,
THE END OF THE TRIGGER CONTACTS
THE INSIDE OF THE TRIGGER GUARD
BOW.

①
DEPENDENT ON HOW TIGHT
THE ACTION SCREWS ARE AND
② NORMAL "ROLL" OF THE ACTION
IN THE STOCK, THIS GUN WILL
FSR AND THEN FOLLOW DOWN.
(NEVER FIRES ON BOLT CLOSE)

ALL SEALS REMOVED - BUT
FIRE CONTROL SPECS OK.

F.C. HAS BEEN REMOVED FROM
ACTION, AND SAFETY FROM F.C. TOO.

BDC - two WASHERS, ONE FRONT.
" REAR.

EXAMINATION OF TRIGGER:
CONTACTS BOW WHEN
PULLED → DUE TO BEND
ALTERATION OF TRIGGER
FINGERPIECE.

TRIGGER pull WITH
TRIGGER BOW REMOVED:

4.52

4.60

4.44

4.58

4.46

⇒ Lots of drag
ON TRIGGER DUE TO
Bow !!