

5-7-93 -1-

Jay's Sports m/700 A6663447

m/700 C.H. 7mm Rem Mag.

Fingerpiece

TRIGGER, BENT REARWARD —

MOVES VERY SLUGGISHLY, — DOES
NOT USUALLY RETURN FROM BEING
PULLED.

FSR TEST:

1) Y
2) Y
3) Y
4) N
5) Y

6) N
7) Y
8) Y
9) Y
10) Y

FSR 8 of 10

Safety falls free-positive detent.

T.P.

6.12
6.28
6.64
6.36
6.46

Stiff & sluggish

Bolt release free.

NO TRICK
NO SCREW

Sear lift full - .0085 to .00825
" " null - .007.

BDC - two washers, one front.
" REAR.

EXAMINATION OF TRIGGER:
CONTACTS BOW WHEN
PULLED, DUE TO BEND
ALTERATION OF TRIGGER
FINGERPIECE.

TRIGGER pull WITH
TRIGGER BOW REMOVED:

4.52

4.60

4.44

4.58

4.46

=> Lots of drag
on trigger due to
Bow !!