

Repair Order Number



Repair Order Number RE00050262	Description/Serial Number A6276587	Repairman - Robert Frink
Account # - R-	Model 700 Center Fire Caliber: 3006	Date Received - 8/19/2002
	BDL W/ PORTED BBL L/ BUTT	Estimate Date - 8/12/2002
	PLATE	Current Date - 8/20/2002
Customer MARK KANE 1233 CHRISTENSEN RD MOUNTAIN HOME. AR 72653 US		Return To MARK KANE 1233 CHRISTENSEN RD MOUNTAIN HOME. AR 72653 US
Phone (H) (870)-492-4021		Fax
Phone (W) (870)-404-1135		Email

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M993	FIRE WHEN BOLT WAS CLOSED 2 X		

		Repair			
Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116	GR-LABOR	20	20	0	N
4000118	GR-CLEAN	1	1	0	Y
4000119	GR-TEST	1	1	0	Y
Service Total:		22	22	0	

ProblemNotes	Action and trigger housing assembly dirty, poorly maintained. Replace trigger assembly at \$20.00. D.S. Customer requests price on a synthetic stock.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date


10 LBS 1 OF 1

REMINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
ILION NY 13357

SHIP

TO:

MARK KANE
1233 CHRISTENSEN RD
MOUNTAIN HOME AR 72653




AR 726 3-00



UPS GROUND

TRACKING #: 1Z 114 813 03 1192 7930



BILLING: P/P

INV#: RE00050262

ASC 05.00 J69X/J64X 16.0A 01/2002