

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs 800-243-9700
Fax 336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

Repair Order Number RE00048006 Account # - R-	Description/Serial Number 6705321 Model 700 Center Fire Caliber: 22250 BDL	Date Received - 7/2/2002 Estimate Date - 6/20/2002 Current Date - 7/8/2002
Customer KING SHOOTERS SUPPLY GOLF 17 WEST 4TH ATLANTIC, IA 50022 US		Return To KING SHOOTERS SUPPLY GOLF 17 WEST 4TH ATLANTIC, IA 50022 US
Phone (H) Phone (W)		Fax Email

REPAIR DOCUMENT

Reported		Problems		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FO		
M238	CLEAN & INSPECT				
M992	FIRES WHEN TAKEN OFF SAFE				

Technician's Comments	
ProblemNotes	Trigger adjustngn screws altered. Trigger covered with a brown sticky substance. Parts working sluggish. Replace trigger assm. at spec. price.

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part Total:		1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	N
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service Total:		22	


10 LBS 1 OF 1

REMINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
ILION NY 13357

SHIP

TO:

KING SHOOTERS SUPPLY GOLF
17 WEST 4TH
ATLANTIC IA 50022




IA 500 1-10



UPS GROUND

TRACKING #: 1Z 114 813 03 1190 6202



BILLING: P/P

INV#: RE00048006

ASC 05.00 J69N/J64N 16.0A 01/2002