

Repair Order Number



Repair Order Number

RE00048006

Account # - R-

Description/Serial Number

6705321

Model 700 Center Fire Caliber: 22250  
BDL

Repairman - Herb Brown

Date Received - 6/14/2002

Estimate Date -

Current Date - 6/20/2002

Customer

KING SHOOTERS SUPPLY GOLF  
17 WEST 4TH

ATLANTIC, IA 50022 US

Return To

KING SHOOTERS SUPPLY GOLF  
17 WEST 4TH

ATLANTIC, IA 50022 US

Phone (H)

Phone (W)

Fax

Email

### Problems

#### Reported

M123 FORWARD TO PRODUCT SERVICE  
FOR INSPECTION  
M238 CLEAN & INSPECT  
M992 → FIRES WHEN TAKEN OFF SAFE

#### Found

M123 FORWARD TO PRODUCT SERVICE F

### Repair

Material # MaterialDesc

Quantity  
Needed

Quantity  
From Inv

Quantity  
From Kit

Warranty  
(Y/N)

Service

4000104 ARMS SERV SHIPPING & HANDLING

Service Total:

0

0

0

Y

0

0

0

1007  
4006  
4016

*Trig adj screws altered  
Components covered with a brown sticky substance.  
Parts working sluggish. Rifle poorly maintained.*

*Date Code  
BY 1/74*

*Replace trigger at 5MP per 20.00*

*Quot*

~~REPAIR ORDER~~  
~~6705321~~  
~~RE00048006~~

Rem 700.

KING SHOOTERS SUPPLY GOLF,  
17 W 4  
ATLANTIC, IA 50022



*Goes off when Bolt is closed.  
or when safety is Released*

Target	Pattern
Date	Date