

Remington Arms Company, Inc.
Attn: Arms Service Dept TPA
14 Hoefler Avenue
Llion, NY 13357

DZ = 9/74

Remington 700 BDL Serial Number: A6201132 Customer

(Larry Pentz) - 10/27/2002 09:04 PM

Last year as I released the safety to eject my shell in the chamber, the gun discharged without my finger anywhere near the trigger. I understand this maybe an inherited problem with Model 700 bolts? Please get back to me ASAP. I would like to get this problem corrected before hunting season.

P.S. I was unable to get the bottom half of the see thru mounts off.

Larry C. Pentz (Home Phone) 717-569-8421
(Work Number) 717-252-3667 Ext. 238
(E-Mail Address)

Ship To Address:

KRB Machinery Company
1058 Cool Creek Road
Wrightsville, Pa 17368
Attn: Larry C Pentz

55237

Could not duplicate -
Altered adjustments,

Quote \$20 under Bolt
Lock modification program
for new TA and cleaning
Action.

FLS 11/11/02

Go ahead - COD

Serial
Number:

A6201132

Model: 700



RE00055237