

File Number:	20177	Arms Service number:	81911	
Last Name:	KROHN	First Name:	DON	
Street:	10961 KASLOF BLVD.	City:	ANCHORAGE	
State:	AK	Zip:	99516	
Work Ph:	907-777-3471	Product Type:	F A T O	
Type Concern:	S	PI PD P S	Concern Code:	1007
Concern:	FIRED ON SAFE RELEASE			
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE	
Assigned To:	SUPRY	Classification:	UND	
Settlement Detail:	REPAIR AT 1/2 MSP			
Date Opened Rem:		Date Opened by P/S:	6/14/2004	
Date of Incident:		Date Closed:		
Date to Analysis:		Date from Analysis:		
Model:	700	Serial:	E6286283	
RAMAC:	700	Litigation:		
Custody:		PreLitigation:		
Time of Modification:	2:45:13 PM	Obsolete:		
Date of Modification:	6/15/2004	Settlement Amount:	\$65.00	
		Caliber:	375	
		Bullet Weight:		
		Manufacturer:	REM	
		Date Mfgd:	6/24/1996	

The trigger and inside the trigger plate are rusty, preventing proper return of trigger. Replace complete TPA, clean action, properly lube, and perform a function test at 1/2 MSP. Repair and shipping document 6/30/2004