

Repair Order Number



Repair Order Number RE00077275	Description/Serial Number 6278293	Repairman - Richard Hilts
Account # - R-	Model 700 Center Fire Caliber: 3006 ADL	Date Received - 2/25/2004
Customer STAN KOTKIEWICZ 3 PETERS PATH		Estimate Date - 2/20/2004
		Current Date - 2/27/2004
Return To STAN KOTKIEWICZ 3 PETERS PATH		
EAST SETAUKET LONG ISLAND, NY 11733 US		EAST SETAUKET LONG ISLAND, NY
Phone (H) (631)-751-5094		
Phone (W)	Fax	Email

Reported		Round	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M992	FIRED WITHOUT TRIGGER BEING PULLED	M992	FIRED WITHOUT TRIGGER BEING PU

Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116	GR-LABOR	20	20	0	N
4000118	GR-CLEAN	1	1	0	Y
4000119	GR-TEST	1	1	0	Y
Service Total:		22	22	0	

ProblemNotes	sear sticks to side walls of trigger due to build up of sticky residue. bolt release sticks clean action install new trigger QUOTE \$20.00 under bolt lock modification program				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date