

Date: 2/19/2004

By: FREO Supry

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Stan Kolkiewicz

R.E. Number: 77275

Reason for inspection: BLM - Program & firing without pulling trigger

FIREARM

Manufacturer: Rem Model: 700

Serial Number: 6278293 Date of Manufacture: 9/69

Overall external condition: fair - trigger guard has a bright mark & gouge on the bottom.

Barrel condition: OK

Receiver condition: OK

Stock condition: OK

Bolt/firing pin condition: OK

Trigger assembly condition:

Engagement: OK

Adjustments/alterations: OK

Other: Caked with Heavy residue -

Headspace: OK

Function evaluation:

Feeding: _____

Extraction/ejection: _____

Trigger pull: _____ OK

Manual safety: _____ OK

Test firing results (if applicable): _____

DISPOSITION

Sent for new TA and cleaning under the bolt lock modification program.

ADDITIONAL COMMENTS

If sear was pushed down the rifle would "follow down" when the action was cycled. The bolt release was difficult to move due to the sticky residue build up. SEAR was sticking to the sidewalls of the TA.