

Remington Arms.

Request that you install

Bolt lock safety.

77275


Have had problems with gun
misfiring + firing without pulling trigger

Have had the bolt looked at by several
dealers who apparently did not fix problems.

Serial
Number:

6278293

Model: 700



RE00077275

Thank you.

Stan Kotbiewicz

SEAR sticks to side walls of TA 3 Peter's Path

due to build up of sticky
residue. Bolt Release sticks,

E. Setanket L.J.

Clean action install new
TA. Quote \$20 under Bolt
Lock modification program.

N.Y. 11733

FLS 2/19/2004

631-751-5094.