

Dear Mr. Kast

In response to the letter I received from you, I would like to state that my problem did not happen from improper adjustment of the trigger assy outside your factory, from improper maintenance of the rifle, or from inadvertent contact with the trigger when the safety was in fire position.

I did notice that the new 700 BDL's can be unloaded with the safety on?

With hunting season just around the corner, I hope you will not take too long examining my rifle.

P.S.

Since I had to remove my scope so you could examine my rifle, I will have to sight it in. It would be nice to include a box of ammunition. I shoot

30-06 150 GRAIN - PTD. SOFT POINT CORE - LOKT.

Thank you

Rick Kimmeth

RICK KIMMETH

144 SHERIDAN AVE

ERIE, PA 16509

S/N 6366508