

April 8, 1994

Remington Arms  
Ilion, New York

Dear Sirs,


On at least three separate occasions, I have had problems with my Remington Model 700ADL bolt-action rifle firing without the trigger being pulled. The rifle has accidentally discharged under the following circumstances:

When the gun is loaded and the safety is on, if I try to lift the bolt to unload the gun the bolt will move slightly, but will not lift completely since the safety is on. If I then flip the safety off, the gun will fire with me never touching the trigger.

The first incident happened within a couple of months after I had purchased the rifle (in 1975 or 1976), so I am relatively certain that the malfunction was not due to abuse or mishandling of the rifle.

When examining the rifle, please note that it has not been fired for approximately 5-10 years.

Thank you,



Bradley P. Kridler  
HCR 61 Box 121  
Sumerduck, Virginia 22742  
Telephone (703)367-4300  
(703)367-5206