

RECEIVING AND ESTIMATING REPORT

CUST NO: 049706 C.O.D

COMMENTS

TAL CUSTOMER ORDER NO.

JM 006435

TE RECEIVED

7/19/91

DATE OPENED

09/24/91

DATE CODE

CH 3-87

SERIAL NUMBER

B6859253

MODEL AND GRADE

700 280

MTN

ORDER

R 91-18831

CESSORIES

W/STUDS

SCOPE BASE

OM:

KIRK, JAMES
BOX 168 RTE 70A
TABERG
USA

NY 13471

SHIP TO:

KIRK, JAMES
BOX 168 RTE 70A
TABERG
USA

NY
13471

COUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

10-4-91

VIA

DOOR

PAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

UN CONDITION:

☐

NEW

☐

SLIGHTLY WORN

☐

VERY WOR.

☐

MISUSED

☐

MARRED

USTOMER'S REQUEST

Gun fired when safety was placed in fire position without pulling trigger

AIN FAULT

Trigger assembly rusted from underneath (also rust on bottom side of barrel). Internal trigger parts not moving properly. cannot duplicate complaint at this time, however, rust on trigger pivot pin could have caused problem.

RTS

Replace trigger assembly at no-charge, as gesture of good-will

REPAIRMAN

DE

GALLERY TESTER

PROOF

DATE

CLEAN

DATE

TEST

DATE

TARGET

DATE

PATTERN

DATE

OFFICE COPY

RD6925 REV. 7/90

PS03729