

RECEIVING AND ESTIMATING REPORT

CUST NO: 047139 C.O.D

COMMENTS
ATTN: ED JOY

INITIAL FPS	CUSTOMER ORDER NO.				
DATE RECEIVED 07/31/91	DATE OPENED 08/07/91	DATE CODE 06 7-86	SERIAL NUMBER B6803725	MODEL AND GRADE 700 270 WIN ADL	ORDER R 91-15225
ACCESSORIES W/STUDS					

FROM: KNAUS, KIRK L
5526 W 4TH AVE
LAKEWOOD
USA CO 80226

SHIP TO: KNAUS, KIRK L
5526 W 4TH AVE
LAKEWOOD
USA CO 80226

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST "The problem is that the rifle on two separate occasions has fired when taking off the safety." *[Handwritten signature]*

MAIN FAULT *Cannot duplicate complaint - no fault found. Trigger and safety assembly operate properly in every respect. Trigger pull 5 1/4 pounds; rear- left .015"*

PARTS *We can return rifle as-is or, offer to replace trigger assembly at 1/2 normal charge, as a gesture of goodwill, if it will help restore confidence in the rifle.*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RECEIVING AND ESTIMATING REPORT

Ed

I had talked to you a couple of months back about my Rifle. The problem is that the Rifle on two Seperate occasions has fired when taking off the safety once on me while sighting it in, and once on my wife while hunting. on both occasions the trigger was pulled w/ the safety on and then when we clicked off the safety afterwards it went off. The rifle is fairly new and has had less than 40 Rounds through it I hope we can find a solution to this problem

Thank You

Sincerely

If you need to send to dealer heres a ss Below.
Mountain Guns
8 W. Jewell ave B-4
Lakewood, Colo. 80227

Kirk L. Knaus
5526 W. 4th ave
Lakewood Colo. 80226
(303) 232-9413

~~cannot replace component - no parts available. trigger and safety assembly operate properly in every respect. Trigger pull 5 1/2 pounds; Rear-Left .015"~~

PARTS	We can return rifle as-is or, if to replace trigger assembly at normal charge, as a gesture of will, it will help restore confidence in the rifle.					
	REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PA
	GALLERY TESTER	DATE	DATE	DATE	DATE	DA

OFFICE COPY

PS03733