

RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL JJM	CUSTOMER ORDER NO.			
DATE RECEIVED 01/09/91	DATE OPENED 01/15/91	DATE CODE LI 2-76	SERIAL NUMBER A6264948	MODEL AND GRADE 700 308 ADL
ACCESSORIES W/STUDS		SCOPE BASE L/REAR SIGHT		
				ORDER R 91-01460

FROM:	SHIP TO:
KUKELKORNS GUN SHOP 795 CAROLINA AVE ORANGEBURG SC 29115	KUKELKORNS GUN SHOP 795 CAROLINA AVE ORANGEBURG SC 29115

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	-------------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST *"see my customer says it has gone off three times when the safety was taken off"*

MAIN FAULT *Trigger assembly has been improperly adjusted instead of feeding - safety missing from all adjustment screws - excessive over-tight, insufficient rear engagement - assembly not operating properly. Closing bolt foot causing firing pin to follow down.*

PARTS *See below repair quotation for new trigger assembly at \$2200.00 cost, no return of good-will.*

REPAIRMAN REW	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD425 REV. 7/90