

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 93-12060

TOTAL	CUSTOMER ORDER NO.		W/CAMO TAPE ON BBL.			
S						
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE	
1/17/93	05/19/93	RY 11-74	6801097		700 270 WIN ADL	
ACCESSORIES W/STUDS						

FROM:	SHIP TO:
<i>[Signature]</i> KLEIN, RICHARD A. 221 CRESTVIEW DR NAMPA	KLEIN, RICHARD A. 221 CRESTVIEW DR NAMPA
ID 83686	ID 83686

CUST NO: 079279 C.O.D

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
					UPS
CONDITION					REPAIR CHARGE
NEW					EXCISE
LIGHTLY WORN					TAX
WORN					INSURANCE
VERY WORN					UPS
UNREPAIRABLE					PARCEL POST
MARRED					TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
LE	A1	B1				
TRIGGER GROUP	ON	B2	Two	occasions	this	gun fired
TRIGGER ASSY.	off	B3	safe	"	E2	F2
REL ASSY.		B4		D1	E3	F3
ASSY.		B5		D2	E4	F4
ID			C1	D3	E5	F5
AL			C2			

FAULT: Unable to duplicate customer concern. Ammunition removed & the action and bolt stop return are jammed up with a sticky substance. Trigger pull 4 3/4 lbs. Bolt stop 1974

Trigger Pull 4 3/4 lbs Bolt stop 1974		COMMENTS			
		Repaired trigger assembly compact at 1/2 normal replacement cost & clear action as per test of good will.			
		Go ahead			
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
OL					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PS03764