

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs
Fax

800-243-9700
336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

Repair Order Number RE00047467 Account # - R-	Description/Serial Number 6667877 Model 700 Center Fire Caliber: 7 MM MAG BDL LEFT HAND	Date Received - 6/10/2002 Estimate Date - 6/5/2002 Current Date - 6/17/2002
Customer ED LAURNEN 12957 NE 39TH STREET BELLEVUE, WA 98005 US Phone (H) Phone (W)	Return To ED LAURNEN 12957 NE 39TH STREET BELLEVUE, WA 98005 US Fax Email	

REPAIR DOCUMENT

Problems			
Reported		Found	
M238	CLEAN & INSPECT	M123	FORWARD TO PRODUCT SERVICE FO
M992	FIRE WHEN SAFE RELEASED	M238	CLEAN & INSPECT
		M239	REPLACE TRIGGER ASSEMBLY

Technical's Comments	
ProblemNotes	could not duplicate, action dirty, ta coated with a sticky residue. clean action and install new ta under bolt lock modification program quote \$20 per product service.

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F32895	700 TRIG ASSB LH	1	Y
Part	Total:	1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	N
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service	Total:	22	


17 LBS 1 OF 1

REMINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
ILION NY 13357

SHIP

TO:

ED LAURNEN
12957 NE 39TH STREET
BELLEVUE WA 98005




WA 982 9-03



UPS GROUND

TRACKING #: 1Z 114 813 03 1189 7302



BILLING: PREPAID

INV#: RE00047467

ASC 3.70 J69K/J64K 14.0 01/2002