

Remington®

DA- 7/80

Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700 - 270 win		Serial Number: B6249262	
Name: DAVID LEMOS		Date of Purchase: APROX. 8/98	
Address (no PO Boxes):: 7530 MILIAS CT.			
City: GILROY		State: CA	Zip: 95020
Phone (Daytime): 408-847-0178		Fax:	
E-mail Address: DAROKOGA@MINDSPRING.COM			
Please describe your problem: WHILE HUNTING IN OCT 2001, I			
CLOSED BOLT ON CHAMBERED ROUNDS GUN DISCHARGED			
THROUGH FLOOR OF P.U. TWO DAYS LATER, WHILE			
TAKING OFF SAFE TO UNLOAD, GUN			
DISCHARGED AGAIN.			
Additional Information: (Ammo type, brand, handload specifications, etc.)			
270 R.P. CASE, CCI 200 PR., 47.8GR. 4895			
130G. SIERRA BT.			
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.			

Serial Number:

B6249262

Model: 700



RE00049826

Could not duplicate.

FIREARM OR IN THE SAME BOX WITH THE FIREARM. ST SEND SPENT SHELLS PLEASE SEND THEM IN A (IP CODE), TELEPHONE AND MODEL AND SERIAL

in shipping and handling. Preferably, (turned.) or damage. Remington is not responsible for these insurance from your carrier.

Altered adjustments
Clean action, install new
TA under bolt lock modification
program. Quote customer \$20.00

<http://www.remington.com/support/repairsvc/repairform.htm>

FLS 7/25/02

7/17/02