

Serial Number:

T6256337

Model: 700



RE00041235

FROM

LEWIS ARMS, LLC  
1575 Hooksett Rd.  
Hooksett, NH 03106-1602  
(603) 485-7334

Service report,

Date called 12/1/00

Owner says twice he pushed the safety forward and the gun fired as he was doing so.

Service & return,

Frank Lee

Brad L

Brad Lewis

2/12/02

Upon receipt we could not duplicate the reported problem, it was noted that more than normal force was required to move the safety. Action & trigger showing slightly dirty. Replaced trigger assembly at no charge.

FORM 61202, RAPIDFORMS, INC. TO REORDER CALL 800-257-8354; FAX 800-451-8113

SPEED-MEMO

C0296

Change 230145

1007  
4040

PS03787