



TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00048982	Description/Serial Number 6647839	Repairman - Robert Frink Date Received - 7/17/2002
Account # - R-	Model 700 Center Fire Caliber: 6 MM BDL	Estimate Date - 7/16/2002 Current Date - 7/18/2002
Customer JERE LIGHT 64 THORNHILL TRAIL BROWNSVILLE, TX 78521 US		Return To JERE LIGHT 64 THORNHILL TRAIL BROWNSVILLE, TX 78521 US
Phone (H) (956)-541-9774 Phone (W)		Fax Email jlight@utbedu

Problems			
Reported		Found	
M238	CLEAN & INSPECT	M123	FORWARD TO PRODUCT SERVICE F
M992	UNINTENTIONAL FIRING	M238	CLEAN & INSPECT
		M239	REPLACE TRIGGER ASSEMBLY

Repair					
<u>Material #</u>	<u>MaterialDesc</u>	<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116	GR-LABOR	20	20	0	N
4000118	GR-CLEAN	1	1	0	Y
4000119	GR-TEST	1	1	0	Y
Service Total:		22	22	0	

ProblemNotes	Sent in for Bolt Lock Modification. Clean action and install a new trigger assembly. FLS 7/15/02.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date


9 LBS 1 OF 1

REMINGTON ARMS CO INC
800 243-8700
14 HOEPLER AVE
ILION NY 13357

SHIP

TO:

JERE LIGHT
64 THORNHILL TRAIL
BROWNSVILLE TX 78521




TX 785 2-01



UPS GROUND

TRACKING #: 1Z 114 813 03 1191 3623



BILLING: P/P

INV#: RE00048982

ASC 05.00 J69X/J64K 16.0A 01/2002