

Serial  
Number:

6647839

Model: 700



RE00048982

18982

64 Thornhill Trail  
Brownsville, Texas 78521  
June 24, 2002

Remington Arms Company, Inc.  
Product Service Department  
14 Hoefler Avenue  
Ilion, N.Y. 13357

Dear Sirs:

Enclosed please find a copy of a Remington repair form for my Remington 700 rifle. You are right to change this system. My rifle has fired when the bolt was lifted to unload it. I had it checked at the time, but found nothing wrong with it. I have been very careful with it since then.

As per your telephone instructions it is being return to you for repair. Please check the trigger assembly also. Enclosed is a check for \$20.00 to defray part of the cost of this repair. If any other repairs are needed, please made them. If any other expenses are incurred please bill me.

Thank you very much for your prompt attention in this matter.

Date Check 6/13  
PX

PX- 6/13

Sent in for bolt lock modification  
clean action & install new TA  
go ahead

FCS 7/15/02

Sincerely,

Jere C. Light

Jere C. Light