

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

Fax

336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00047921 Account # - R-	Description/Serial Number 6258681 Model 700 Center Fire Caliber: 3006 ADL	Date Received - 6/14/2002 Estimate Date - Current Date - 6/20/2002
Customer SHARON LOHT 404 BOYD ST GOLDEN, CO 80403 US Phone (H) (303)-279-8940 Phone (W)	Return To SHARON LOHT 404 BOYD ST GOLDEN, CO 80403 US Fax Email	

Reported		Problems	Found
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M239	REPLACE TRIGGER ASSEMBLY
M238	CLEAN & INSPECT		

Technician's Comments	
Problem/Notes	Could not duplicate. Trigger assm. coated with sticky residue, debris and rust. Under side of action also same condition. Replace trigger assm. clean action, bolt lock safety modification.

Parts and Labor		Quantity	Warranty (Y/N)
Material #	Material Description		
Part			
F97490	700 SS TRIG ASSB RH	1	Y
Part Total:		1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	N
4000118	GR-CLEAN	1	Y
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service Total:		23	


10 LBS 1 OF 1

REMINGTON ARMS CO. INC.
800 243-9700
14 HOEFLER AVE
ILION NY 13357


SHIP

TO:

SHARON LOHT
404 BOYD ST
GOLDEN CO 80403-1513




CO 802 9-06



UPS GROUND

TRACKING #: 1Z 114 813 03 1190 0440



BILLING: PREPAID

INV#: RE00047921

ASC 3.70 J69K/J64K 14.0 01/2002