

Repair Order Number



Repair Order Number RE00087318	Description/Serial Number G6289787	Repairman - Herb Brown Date Received - 11/5/2004
Account # - R-	Model 700 Center Fire Caliber: 300 REM SA ULTRA MAG BDL FLUTED	Estimate Date - 11/3/2004 Current Date - 11/9/2004
Customer LAWMENS SAFETY SUPPLY INC SUITE 120 3315 BROAD RIVER RD COLUMBIA. C.29210 US		Return To LAWMENS SAFETY SUPPLY INC SUITE 120 3315 BROAD RIVER RD COLUMBIA. C 29210 US
Phone (H) (803)-798-2253 Phone (W)	Fax (803)-798-6107 Email	

Reported		Problems Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M992	FIRED WHEN SAFETY PUSHED OFF		

Material #		MaterialDesc		Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part							
F26345		700 TRIG ASSB RH		1	1	0	N
Part Total:				1	1	0	
Service							
4000294		GR-CHECK TPA		1	1	0	Y
4000104		ARMS SERV SHIPPING & HANDLING		0	0	0	N
4000119		GR-TEST		1	1	0	N
Service Total:				2	2	0	

ProblemNotes		All 3 trigger adjusting screws re-set, altered. Quote 1/2 msp. new trigger assm.			
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date