

MARCIA LEVY

SHOOTING COMPANY

BOX 178

COLORADO 81641

303 878-3468

Remington Arms Inc.

Customer Service

14 Hoculen Road

Ilion, NY 13357

Tel: 315 895 7791

August 11, 1994

REF.: FIREARM MODEL 700 BDL SERIAL # B6499277 7MM REM MAG. LEFT HAND BOLT

Dear Customer Service,

I am returning my rifle to you for service on the firing mechanism because the rifle misfired in succession for my brother in law who used it a few years ago while hunting on our ranch (October 1990). It seems that after the safety is moved forward to the Fire Position the gun would sometimes fire. This happened more than once when we tested the weapon then. At the time, we put it down to mishandling or dirt in the mechanism. It also occurred for me once the other day when I made a test after reading the May 23, 1994 story in Business Week. I could not get the gun to repeat the fault. I can not in good conscience continue to use this weapon or loan it to anyone knowing that the trigger mechanism might misfire again. Fortunately we all practice gun safety conscientiously and no one was hurt.

I am returning it with the scope dismounted and the bolt removed and taped separately to the rifle. Please repair or replace the weapon as soon as possible.

Either way, please return it to:

Sheriff's Custom Arsenal

Mr. Bruce Nottingham

442 Market Street

Meeker Colorado 81641

Tel: 303 878 3160.

Mr. Nottingham is a licensed FFL, and if you need his number before shipping please call him at the above number.

Sincerely,

William P. Levy

PS03864