

RECEIVING AND ESTIMATING REPORT				COMMENTS		ORDER	
INITIAL FDC		CUSTOMER ORDER NO.		W/LEUPOLD SCOPE		R 74-16361	
DATE RECEIVED 05/20/94	DATE OPENED 05/20/94	DATE CODE CK 4/90	SERIAL NUMBER C6534027	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06	SPRG.	
ACCESSORIES W/STUDS		SCOPE MNTS		SCOPE BASE		L/SIGHTS	
FROM: LANUNZIATA, LOUIS J. 1700 RIVERVIEW DR. P.O. BOX 1718 BURGAW NC 28425				SHIP TO: LANUNZIATA, LOUIS J. 1700 RIVERVIEW DR. P.O. BOX 1718 BURGAW NC 28425			
CUST NO 1097632 C.O.D.							
ACCOUNT NUMBER		ACCOUNT NUMBER NC		WRITE ☐		FROM DATE ESTIMATED VIA UPS	
GUN CONDITION						REPAIR CHARGE	
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED						EXCISE TAX INSURANCE UPS PARCEL POST TOTAL	
CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT	
CYCLE	A1	B1					
TRIGGER GROUP		B2			E1	F1	
BOLT ASSY.		B3					
BARREL ASSY.		B4		D1	E3	F3	
REC. ASSY.		B5			E4	F4	
WOOD			C1	B3	E5	F5	
METAL			C2				
MAIN FAULT <i>Left side R40 - Could not duplicate the customer problem.</i> <i>Opinioner did not want that the trigger adjustment and rear sight adjustment were done</i> <i>but the contact seemed and have been in set. trigger part - 2 1/2 lbs. a little over</i> <i>min. specification. Also found a white lubricant on the trigger housing which is</i> <i>the surrounding the trigger housing.</i>							
PARTS				COMMENTS			
				<i>Replace trigger housing and</i> <i>then adjust it to normal last, as</i> <i>per the spec.</i> <i>to normal.</i>			
REPAIRMAN				PROOF	CLEAN	TEST	TARGET
GALLERY TESTER				DATE	DATE	DATE	DATE

OFFICE COPY

RD8925 REV. 1/84

to A/S

5/25/94