

5/10/94

Mr. Smith,

After calling your Custom Service Department, I am returning to you this 700 series 38-06 revolver I bought last year or the year before. It has fired on me while I put the bolt back and when I removed the safety. This is a very dangerous place for it if you can replace it. I have bought Remington guns all my life and this is the first such problem I have had. Thank you.

Respectfully,

Dr. Louis J. Lanunziata

Louis J. Lanunziata

1700 Riverview Drive

P.O. Box 1718

Burgaw, N.C. 28425

Return

to