

RECEIVING AND ESTIMATING REPORT

COMMENTS

Dotter

ORDER
R 93-09468

INITIAL

CUSTOMER ORDER NO.

PS

065244

DATE RECEIVED

04/06/93

DATE OPENED

04/08/93

DATE CODE

BS 1-69

SERIAL NUMBER

6205318

NEW SERIAL NUMBER

MODEL AND GRADE

700 270 WIN

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

LONGACRES
358 CHESTNUT ST
ABILENE

TX 79602

SHIP TO:

LONGACRES 2. LC F. Suppy
358 CHESTNUT ST
ABILENETX
79602

CUST NO: 006401 ILION L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

4/29/93 UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

MAIN FAULT

ARTS

COMMENTS

Customer states that gun goes off when safety is pulled

Unable to duplicate as described. However, ammunition inserted
a heavy sticky substance on bolt stop release and main trigger housing
Caused sticky substance found on main cam, blocking trigger movement.
Trigger adjustment now correct with no problem.

Replace trigger assembly complete
at 1/2 normal replacement cost
& clean action as per request of
Customer's gun

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/92

PS03908