

Remington.

REMINGTON ARMS COMPANY INC

PAGE 51



SPORT

PARTS: (315) 895-7493

SOLD TO

REPAIR

LEWIS, D A
18130 ALTA VISTA
BUENAVISTA

DAVID A. OR JAN LEWIS
18130 ALTA VISTA 719/395-8295
BUENA VISTA, CO 81211

1943

82-7512/3020

PAY *Remington Arms Company Inc* \$ 29.61
TO THE ORDER OF *Twenty-nine and 61/100*



COLORADO STATE
EMPLOYEES' CREDIT UNION
1721 Highway 50 W. (719) 543-9825
Pueblo, Colorado 81008

FOR

⑆302075128⑆

40380086⑆

1943

THIS IS AN ESTIMATE TO REPAIR OR RECONDITION THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW. RETURN THE FIRST COPY TO REMINGTON ARMS CO., INC., ILION, NY, 13357. KEEP THE SECOND COPY AS YOUR RECEIPT.

REPAIR TO TAKE ABOUT 6 WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN THIRTY DAYS, WE SHALL RETURN THE ITEM(S) AS RECEIVED.

700 270 WIN
L/STUDS

SERIAL NUMBER: 6760251

ATTN: JIM STEKL

CUSTOMER REQUEST:

"...DISCHARGED WHEN I CLOSED THE CHAMBER ON A LIVE ROUND"

MAIN FAULT FOUND:

AS RECEIVED THE TRIGGER WOULD NOT RETRACT AND THE BOLT STOP WAS NEARLY INOPERATIVE. INSPECTION REVEALED THAT THE TRIG ASSEM WAS CONTAMINATED WITH A STICKY RESIDUE AS WAS THE BOLT STOP. INTERNAL TRIGGER PARTS ARE NOT MOVING FREELY TRIG PULL SLDS. SEAR LIFT .007".

1 0026345

TRIGGER ASSEM RH

THIS GUN HAS NOT BEEN PROPERLY MAINTAINED AND CLEANED CLEAN PRESENT TRIGGER ASSM, IF POSSIBLE, IF NOT OFFER REPLACEMENT TRIGGER ASSEMBLY AT 1/2 NORMAL COST AS GESTURE OF GOOD WILL CLEAN, TEST
JJB:LHS

23.00

TOTAL REPAIR CHARGE
TAXES

23.00
1.61

INSURANCE
PARCEL POST

5.00

TOTAL
CHARGES

29.61

☐ PLEASE RETURN REMITTANCE WITH THIS COPY OR SHIPMENT WILL BE MADE C.O.D.

NOTE: IF YOU DESIRE ANY CHANGE USE THE REVERSE SIDE FOR YOUR COMMENTS AND MARK THIS BLOCK.



ALL THIS IS AN ESTIMATE TO REPAIR OR RECONDITION THE ITEMS LISTED ABOVE. IF SATISFACTORY, PLEASE SIGN AND RETURN THIS COPY TO: REMINGTON ARMS COMPANY, INC. ILION, NEW YORK 13357

QUOTATION COPY

CUSTOMER'S SIGNATURE

PS03972