

RECEIVING AND ESTIMATING REPORT

CUST NO: 006946 TLION		COMMENTS	
INITIAL	CUSTOMER ORDER NO.		
JM			
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER
8/28/91	09/03/91	DU 9-71	6481228
ACCESSORIES		MODEL AND GRADE	ORDER
		700 7MMAG BDL	R 91-17220
W/STUDS		SCOPE BASE	

FROM:	SHIP TO:
LEXINGTON HDWE CO. 23 SOUTH MAIN ST. LEXINGTON USA	LEXINGTON HDWE CO. 23 SOUTH MAIN ST. LEXINGTON USA
VA 24450	VA 24450

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					9/17/91	UPS

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST: "This rifle fires at times when doing test also at times when taking off safety, and not "touching" trigger."

IN FAULT: Cannot duplicate above complaints. However, removal of action from stock revealed that the receiver of the action is extremely oily and dirty; also, the trigger assembly is contaminated with excessive lubrication, both wet and dried. Rifle has not been properly maintained. Trigger pull 5 pounds; star. lift .003"

RTS

- 1) Clean entire rifle
- 2) Clean trigger assembly, if possible; if not, purchase new assembly at the price as gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
RTX2					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PS03980