

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-22296INITIAL
FPS

CUSTOMER ORDER NO.

ATTN: JIM STEKL
W/BTM PART OF SCOPE MNTS

DATE RECEIVED 10/20/92 DATE OPENED 10/23/92 DATE CODE 00 7-77 SERIAL NUMBER A6478653 NEW SERIAL NUMBER MODEL AND GRADE 700 30-06 BDL

ACCESSORIES W/STUDS SCOPE BASE

FROM:

LIEPSE, ROB
133 EAST 5TH AVE
LONGMONT

CO 80501

SHIP TO:

LIEPSE, ROB
133 EAST 5TH AVE
LONGMONTCO
80501

CUST NO 068732 C.O.D. L

ACCOUNT NUMBER ACCOUNT NUMBER N/C WRITE ☐ CLEAN/TEST PROM. DATE ESTIMATED VIA UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☒ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN AMMO FUNCTION FINISH ACCURACY FIT INSPECT

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3				
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT No fault found - complaint could not be duplicated after many attempts. Rifle and trigger assembly appear to operate normally, in every respect.

Trigger pull 5 1/2 pounds, over lift on

PARTS

COMMENTS

Offer the following options & return with as-is
1) install new trigger assembly at 1/2 normal cost. At customer's good-will if that will restore confidence in the rifle.

CHAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
CLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

FD0825 REV. 1/82

PS04018