

RECEIVING AND ESTIMATING REPORT ✓

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 12/21/90	DATE OPENED 01/02/91	DATE CODE CU 4-71	SERIAL NUMBER 6419703	MODEL AND GRADE 700 22-250 ADL		ORDER R 91-000	
ACCESSORIES SCOPE BASE							

FROM: JIM MASTERS WESTERN STORES
400 GILMER ST
SULPHUR SPRINGS TX 75482

SHIP TO: JIM MASTERS WESTERN STORES
400 GILMER ST
SULPHUR SPRINGS TX 75482

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☒ VERY WORN ☒ MISUSED ☐ MARRED					
CUSTOMER'S REQUEST					

"Discharges prematurely when bolt closed after locking"

MAIN FAULT: *Cannot duplicate complaint. However, trigger assembly is extremely dirty and has been improperly adjusted out of factory as evidenced by foreign sealant on adjustment screws. Trigger pull 6 pounds, insufficient over-travel, excessive over-engagement. Rifle has not been properly maintained.*

Offer replacement trigger assembly at 1/2 normal cost, as gesture of good-will.

REPAIRMAN L & W	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

stek/

RD6923 REV. 7