

Remington.

TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00093726	Description/Serial Number B6666701	Repairman - Herb Brown Date Received - 2/28/2005
Account # - R-	Model 700 Center Fire Caliber: 243 WIN ADL	Estimate Date - Current Date - 3/4/2005
Customer MARTINS SPORTS 1016 17TH AVENUE MONROE, WI 53566 US		Return To MARTINS SPORTS 1016 17TH AVENUE MONROE, WI 53566 US
Phone (H) (608)-325-3370 Phone (W)		Fax Email

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M239	REPLACE TRIGGER ASSEMBLY	M239	REPLACE TRIGGER ASSEMBLY
M992	FIRES WHEN TAKEN OFF SAFE		

Material #		MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part						
F26345		700 TRIG ASSB RH	1	1	0	N
Part Total:			1	1	0	
Service						
4000254		GR-FIREARM REPLACEMENT	1	1	0	Y
4000104		ARMS SERV SHIPPING & HANDLING	0	0	0	N
4000119		GR-TEST	1	1	0	N
Service Total:			2	2	0	

ProblemNotes	Trigger adjusting screws altered- reset. Replase trigger assm. at 1/2 normal charge.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date