

RECEIVING AND ESTIMATING REPORT

COMMENTS

Stekl

ORDER
R92-19540

INITIAL PS	CUSTOMER ORDER NO.					
DATE RECEIVED 19/16/92	DATE OPENED 09/28/92	DATE CODE DS 9-69	SERIAL NUMBER 6273958	NEW SERIAL NUMBER	MODEL AND GRADE 700 270 WIN	BDL
ACCESSORIES W/STUDS	SCOPE BASE		L/SIGHTS			

ROM:

SHIP TO:

MCCLELLANDS GUN SHOP
DIVISION OF REMCO
1533 CENTERVILLE ROAD
DALLAS

TX 75228

MCCLELLANDS GUN SHOP
DIVISION OF REMCO
1533 CENTERVILLE ROAD
DALLAS

TX

75228

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	CUST NO: 006612 WILM	PROM. DATE	ESTIMATED	VIA UPS
WRITE ☐ CLEAN/TEST					
GUN CONDITION ☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE					REPAIR CHARGE
					EXCISE
					TAX
					INSURANCE
					UPS
					PARCEL POST
					TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *Could not duplicate complaint after many attempts. Rifle trigger assembly operates properly in lock, suggest trigger pull - 3 1/2 pounds & rear lift 0020*

ARTS *Trigger pull - 3 1/2 pounds & rear lift 0020*

COMMENTS *We can either properly adjust present trigger assembly, or install new trigger assembly at 2 second cost, even though there is nothing wrong with present assembly as a question of good-will, if that will better restore confidence in the rifle. Offer customer above options*

REPAIRMAN RBS	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

PS04056