

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

92-10689

INITIAL
JJM

CUSTOMER ORDER NO.

STAINLESS STEEL

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

04/20/92

04/27/92

6711779

700

17REM

BDL

ACCESSORIES

W/STUDS

L/SIGHTS

OZ 7-75 2ND TIME

FROM:

SHIP TO:

MASCHMEDT & ASSOCIATES INC
12304 32ND AVE NE
SEATTLE

WA 98125

MASCHMEDT & ASSOCIATES INC
12304 32ND AVE NE
SEATTLEWA
98125

CUST NO: 060617 CJD.DL

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

Trigger assembly has sprung from unknown source - internal parts are not moving freely nor properly. Complaint could not be duplicated, however, it is very possible that safety combination could at some time cause this problem. Rifle has not been properly maintained.

PARTS

COMMENTS

Replace trigger assembly at no charge, as gesture of good-will.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/92

PS04072